





FDM 8 25 10 inverted relay.vi


C:\FDM\LV Working\FDM 8 25 10 inverted relay.vi

Last modified on 8/28/2010 at 10:56 PM

Printed on 8/30/2010 at 10:47 AM



FDM amplitude	FDM FOM	FDM S/N	HIGH FOM	MSR FAIL	time of last measurement	MSR NO.	Error Code
2.1 Volts	1.0E-6	24.3 dB	●	●	10:46:49 AM 8/30/2010	2286	0



F SCALAR 53742.6

NanoTesla

PRECESSION FREQUENCY 2287.460 Hz

OPERATE ● STOP RUN

Sample frequency 10000.354 Hz

Number of Samples 11000

Msr Window 1.1 seconds