





FDM 8 25 10 inverted relay.vi


C:\FDM\LV Working\FDM 8 25 10 inverted relay.vi

Last modified on 8/28/2010 at 10:56 PM

Printed on 8/30/2010 at 9:17 PM



FDM amplitude	FDM FOM	FDM S/N	HIGH FOM	MSR FAIL	time of last measurement	MSR NO.	Error Code
2.0 Volts	5.0E-7	35.7 dB	<span style="color: green;">●</span>	<span style="color: green;">●</span>	09:17:07 PM 8/30/2010	215	0



F SCALAR 53765.0

NanoTesla

PRECESSION FREQUENCY 2288.411 Hz

OPERATE ● STOP RUN

Sample frequency 10000.354 Hz

Number of Samples 11000

Msr Window 1.1 seconds