





FDM 3 9 10 USB6008.vi

C:\FDM\LV working\FDM 3 9 10 USB6008.vi

Last modified on 3/9/2010 at 8:56 PM

Printed on 3/9/2010 at 10:24 PM



FDM amplitude FDM FOM

HIGH FOM MSR FAIL

current time

MSR NO.

Error Code

0.97 Volts


1.0E-6



10:23:10 PM
3/9/2010

71

0



PRECESSION FREQUENCY

F SCALAR 53828.9

NanoTesla

2291.133 Hz

OPERATE

STOP RUN

Sample frequency 10000.354 Hz

Number of Samples 11000

Msr Window 1.1 seconds