





FDM 8 25 10 inverted relay.vi


C:\FDM\LV Working\FDM 8 25 10 inverted relay.vi

Last modified on 8/31/2010 at 2:11 PM

Printed on 8/31/2010 at 8:44 PM



FDM amplitude	FDM FOM	FDM S/N	HIGH FOM	MSR FAIL	time of last measurement	MSR NO.	Error Code
1.6 Volts	5.0E-7	31.9 dB	●	●	08:43:38 PM 8/31/2010	410	0



F SCALAR 53766.0

NanoTesla

PRECESSION FREQUENCY 2288.455 Hz

OPERATE STOP RUN

Sample frequency 10000.354 Hz

Number of Samples 11000

Msr Window 1.1 seconds